











| | | | | |
|--|--|---|--|---|
| 3,5 X30 YHB  4 ADET | 3,5 X16 YHB  6 ADET | BETON DÜBELİ  1 ADET | DEPREM DEMİRİ  1 ADET | |
| 4X50 YHB  1 ADET | KAVELA  18 ADET | RAFİX MILİ  12 ADET | MINİFIX ÇEKTİRME (15 mm)  26 ADET | KENDİNDEN DÜBELLİ MINİFIX VİDASI (ø10)  26 ADET |

444 6 999
Toll-free information line only
for domestic calls-Türkiye





PLEASE RETAIN THE LABEL INFORMATION ON THE PACKAGES. DO NOT START ASSEMBLY IF THERE ARE ANY MISSING ITEMS IN THE PACKAGE.
THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY DAMAGES THAT MAY BE INCURRED DURING THE ASSEMBLY PROCESS AND LATER ON DUE TO THE MISUSE OF BUYERS.
KOLİ ÜZERİNDEKİ ETİKET BİLGİLERİNİ SAĞLAYINIZ. KOLİLERİNDE EKŞİK PARÇALAR SAĞIŞA, LÜTFEN MONTAJA BAŞLAYINIZ.
MONTAJ ESNASINDA VE DAMASINDA KULLANILCI HATALARINDAN DOĞRUCAK HESAPLARDA ÜRETİCİ FİRMA SORUMLU DEĞİLDİR.


2



4



3



5

