




M4x22 KULP VİDASI	KULP	50 MM KABİN VİDASI	3.5X16 SUNTA VİDASI	3.5X35 SUNTA VİDASI	M6x80 YHB CİVATA
4 ADET	2 ADET	2 ADET	2 ADET	8 ADET	8 ADET
M4x60 SUNTA VİDASI	PLASTİK POLİGRİT	METAL ARKALIK L BİRLEŞTİRME	4x25 YHB VİDA	M6,3x13,5 YHB CİVATA	KAVELA
6 ADET	4 ADET	2 ADET	4 ADET	8 ADET	14 ADET
	RAFİX MİLİ	MİNİFİX VİDA	MİNİFİX ÇEKTİRME (18 mm)	HETTİCH PİMLİ RAY (SOL)	HETTİCH PİMLİ RAY (SAĞ)
	4 ADET	18 ADET	18 ADET	2 ADET	2 ADET

PLEASE RETAIN THE LABEL INFORMATION ON THE PACKAGES. DO NOT START ASSEMBLY IF THERE ARE ANY MISSING ITEMS IN THE PACKAGE.

THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY DAMAGES THAT MAY BE INCURRED DURING THE ASSEMBLY PROCESS AND LATER ON DUE TO THE MISUSE OF BUYERS.
KOLİ ÜZERİNDEKİ ETİKET BİLGİLERİNİ SAKLAYINIZ. KOLİ İÇERİSİNDE EKSİK PARÇA YARSA, LÜTFEN MONTAJA BAŞLAMAYINIZ.

MONTAJ ESNASINDA VE DAHA SONRA KULLANICI HATALARINDAN DOĞACAK HASARLARDA ÜRETİCİ FİRMA SORUMLU DEĞİLDİR.



444 6 999

Toll-free information line only
for domestic calls-Türkiye



