




| NO | KOD/ CODE        | PARÇA ADI              | NAME                       | ADET/PIECE | KUTU/BOX |
|----|------------------|------------------------|----------------------------|------------|----------|
| 1  | 2AST001KA671916  | CATILMIS KONSOL AYNASI | MOUNTED MIRROR FOR CONSOLE | 1          | 1        |
| 2  | 2AST001ATM215715 | AYNALIK ARKA TUTUCU    | MIRROR BACK HOLDER         | 2          | 1        |
| 3  | 2AST001KA671840  | AYNALIK ALT KAYIT      | MIRROR BOTTOM FRAME        | 1          | 1        |
| 4  | 2AST001KA671841  | AYNALIK YAN KAYIT      | MIRROR SIDE FRAME          | 2          | 1        |



PLEASE RETAIN THE LABEL INFORMATION ON THE PACKAGES. DO NOT START ASSEMBLY IF THERE ARE ANY MISSING ITEMS IN THE PACKAGE.  
THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY DAMAGES THAT MAY BE INCURRED DURING THE ASSEMBLY PROCESS AND LATER ON DUE TO THE MISUSE OF BUYERS.  
KOLİ ÜZERİNDEKİ ETİKET BİLGİLERİNİ SAKLAYINIZ. KOLİ ÜÇERİSİNDE EKSIK PARÇA YARSA, LÜTFEN MONTAJA BAŞLAMAYINIZ.  
MONTAJ ESNASINDA VE DAHA SONRA KULLANICI HATVALARINDAN DOĞRUK KULLANILARLA ÜRETİCİ FİRMA SORUMLU DEĞİLDİR.

