





**ASTORIA MIRROR FOR CHEST OF DRAWERS**  
AST01SA671  
**ASTORIA ŞİFONYER AYNASI**

**RV02**

TOPLAM KUTU  
TOTAL BOXES  
COLLI ZAHL

**1**

NO	KOD/CODE	PARÇA ADI	NAME	ADET/PIECE	KUTU/BOX
1	ZAST001SFA671916	ÇATILMIŞ ŞİFONYER AYNASI	MOUNTED MIRROR FOR CHEST OF DRAWER	1	1
2	ZAST001ATM215715	AYNALIK ARKA TUTUCU	MIRROR BACK HOLDER	2	1
3	ZAST001SFA671840	AYNALIK ALTI KAVİT	MIRROR BOTTOM FRAME	1	1
4	ZAST001SFA671841	AYNALIK YAN KAVİT	MIRROR SIDE FRAME	2	1



PLEASE RETAIN THE LABEL INFORMATION ON THE PACKAGES. DO NOT START ASSEMBLY IF THERE ARE ANY MISSING ITEMS IN THE PACKAGE.  
THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY DAMAGES THAT MAY BE INCURRED DURING THE ASSEMBLY PROCESS AND LATER ON DUE TO THE MISUSE OF BUYERS.  
KULLANIMDEN ÖNCE ETİKET BİLGİLERİNİ SAKLAYINIZ. KOLİLERİNDE EKŞİK PARÇA VARSA, LÜTFEN MONTAJA BAŞLAMAYINIZ.  
MONTAJ ESNASINDA VE DAHA SONRA KULLANICI HATALARINDAN DOĞACAKI HASARLARDA ÜRETİCİ FİRMAYA SORUMLU DEĞİLDİR.



